

Lyle Elementary School

Dallas SD 2

Polk_sch08A

Building Type		County	
School		Polk	
Street			
185 SW Levens St			
City	State	Zip	
Dallas	OR	97338	
Latitude		Longitude	
44.92839		123.3202	
Tracking Code		Inspection Date	
RVS in 2006		7/20/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Lyle Elementary School

Final RVS Score

Final Type

Final Score

W2

0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
430	1950	1950	1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
48077	2	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Steps in Elevation View: 2 to 3 Changes
Out of Plane Lateral-Force-Resistance Elements	Building On Hill or Sloped Site
None	Short Columns

Falling Hazards	Poor Conditions
None	None
None	None
None	None



E Vertical Irregularity Secondary

E Vertical Irregularity Tertiary
some concern over these short columns - do they support gravity loads above?

SW Plan Irregularity Primary



SW Plan Irregularity Primary