

Oakdale Heights Elementary School

Polk_sch11A

Dallas SD 2

Building Type	County	
School	Polk	
Street		
1275 SW Maple St		
City	State	Zip
Dallas	OR	97338
Latitude	Longitude	
44.91614	123.33754	
Tracking Code	Inspection Date	
RVS in 2006	7/20/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	0	-0.5	0	0	-0.4	0	0	2.9
Secondary	RM1	2.8	0	-0.5	0	0	-0.4	0	0	1.9
Tertiary		0	0	0	0	0	0	0	0	0

Oakdale Heights Elementary School

Final RVS Score

Final Type	Final Score
RM1	1.9

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Oakdale Heights Elementary School

Polk_sch11A

Enrollment 420	Year Built (Field Verified) 1975	Year Built (Alt. Source) 1970	Est. Decade Built 1970
Total Area (square ft) 46370	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Non-Parallel System Reentrant Corners: Other None		Vertical Irregularities Building On Hill or Sloped Site Steps in Elevation View: Single Change None	
Falling Hazards None None None		Poor Conditions None None None	
			
NE Plan Irregularity Primary	SW Vertical Irregularity Primary steps in elevation also, and reentrant corners	SE Other the play area that is between each segment of A-- almost might be considered a gym (three walls).	
			
S General Site			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries