

Building Type	County	
School	Polk	
Street		
1075 8th St NW		
City	State	Zip
Salem	OR	97304
Latitude	Longitude	
44.94728	123.05958	
Tracking Code	Inspection Date	
Structural Engineering Report		
9/15/2006		



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	PC1	2.6	0	-0.5	0	0	0	-0.6	0	1.5
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Walker Middle School

Final RVS Score

Final Type	Final Score
PC1	1.5

FEMA-154 Collapse Potential

Moderate (>1%)

No
Planview
Available



Walker Middle School

Polk_sch15A

Enrollment 968	Year Built (Field Verified) 1960	Year Built (Alt. Source) 1960	Est. Decade Built
Total Area (square ft) 139920	Number of Stories 2	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
<input type="text"/>		<input type="text"/>	
<input type="text"/>		<input type="text"/>	
<input type="text"/>		<input type="text"/>	
Falling Hazards		Poor Conditions	
<input type="text"/>		<input type="text"/>	
<input type="text"/>		<input type="text"/>	
<input type="text"/>		<input type="text"/>	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries