

# South Sherman FPD

South Sherman FPD

Sher\_fir02A

Building Type Fire - RFPD	County Sherman	
Street 109 Sw 2nd St		
City Grass Valley	State OR	Zip 97029
Latitude 45.35956	Longitude 120.78542	
Tracking Code RVS in 2006	Inspection Date 8/28/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S3	3.8	0	-0.5	0	0	0	0	0	3.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

South Sherman FPD

## Final RVS Score

Final Type	Final Score
S3	3.3

## FEMA-154 Collapse Potential

Low (<1%)

No  
Planview  
Available



OregonGeology

# South Sherman FPD

Sher\_fir02A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1982	2000
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: L Shaped		None	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	



W Building Name  
AND BUTLER LOGO



NW Plan Irregularity Primary



SW Building Name



E Elevation View



SE Elevation View



NE General Site  
OLD FS USED FOR STORAGE-118 1ST



NW General Site  
BACK OF OLD FS



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries