

Rufus VFD

Sher_fir05A

City of Rufus

Building Type		County	
Fire - City		Sherman	
Street			
400 Main St			
City	State	Zip	
Rufus	OR	97050	
Latitude		Longitude	
45.69325		120.73509	
Tracking Code		Inspection Date	
RVS in 2006		8/28/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	0	0	0	0	-0.8	0	0	2.8
Secondary	C3	3.2	0	0	0	0	-0.6	0	0	2.6
Tertiary		0	0	0	0	0	0	0	0	0

Rufus VFD

Final RVS Score

Final Type

Final Score

C3

2.6

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No

Plan Irregularities	Vertical Irregularities
None	None
None	None
None	None

Falling Hazards	Poor Conditions
None	Cracks
None	None
None	None



NW Elevation View

W Building Quality
stairstep crackS Poor Condition
pier cracks

SE Elevation View



S Elevation View

