

Building Type	County
EOC-Public Safety Answering P	Tillamook
Street	
2311 Third Street	
City	State Zip
Tillamook	OR 97141
Latitude	Longitude
45.4561	123.8403
Tracking Code	Inspection Date
RVS in 2006	9/8/2006



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	0	0	0	0	-0.6	0	2.2
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Tillamook 911 Center

## Final RVS Score

Final Type	Final Score
RM1	2.2

## FEMA-154 Collapse Potential

Low (&lt;1%)

No  
Planview  
Available



Oregon Geology

# Tillamook 911 Center

Till\_eoc01A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1993	1993	1990
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
None		None	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
N Pounding Potential NO POUNDING, 6" GAP		N Building Name	
			
N Seismic Upgrade SEISMIC JT COVER		N Elevation View SEISMIC JT ON ROOF	
			
N Field Verified Year Built		N Field Verified Year Built	
			
SE General Site 2005 PORTIONS		SE General Site 2005 PORTIONS	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries