

# Tillamook Fire Dist Main Station #71

Tillamook FD

Till\_fir01A

Building Type Fire - RFPD	County Tillamook	
Street 2310 4th St		
City Tillamook	State OR	Zip 97141
Latitude 45.45575	Longitude 123.84025	
Tracking Code RVS in 2006	Inspection Date 9/8/2006	



Seismicity Zone: Very High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	2.4	0	-0.8	0	2.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Tillamook Fire Dist Main Station #71

## Final RVS Score

Final Type	Final Score
W2	2.9

## FEMA-154 Collapse Potential

Low (<1%)

No  
Planview  
Available



OregonGeology

# Tillamook Fire Dist Main Station #71

Till\_fir01A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1982	1982	1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes	
Lateral-Force-Resistance in One Direction Only		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
W	Number of Stories	S	Plan Irregularity Primary
			
S		Primary Structural Type WOOD GARAGE WALLS	
E	Plan Irregularity Secondary	NE	Vertical Irregularity Primary



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries