

Tillamook Fire Station South Prairie Station #72

Till_fir09A

Tillamook FD

Building Type Fire - RFPD	County Tillamook	
Street 9975 South Prairie Rd		
City Tillamook	State OR	Zip 97141
Latitude 45.3833	Longitude 123.80275	
Tracking Code RVS in 2006	Inspection Date 9/7/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	0	0	0	2.4	0	-0.8	0	5.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Tillamook Fire Station South Prairie
Station #72

Final RVS Score

Final Type	Final Score
W2	5.4

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Tillamook Fire Station South Prairie Station #72

Till_fir09A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1976	1990
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
840	1	No	No
Plan Irregularities		Vertical Irregularities	
None		None	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
SW Building Name		W Primary Structural Type PLWD SHEATHING	
		NE Elevation View	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries