

Netarts - Oceanside RFPD Station #62 Oceanside

Till_fir10A

Netarts - Oceanside RFPD

Building Type Fire - RFPD	County Tillamook	
Street 1559 Pacific Ave		
City Oceanside	State OR	Zip 97134
Latitude 45.46027	Longitude 123.96924	
Tracking Code RVS in 2006	Inspection Date 9/12/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	-0.5	0	0	-0.4	0	0	1.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Netarts - Oceanside RFPD Station
#62 Oceanside

Final RVS Score

Final Type	Final Score
RM1	1.9

FEMA-154 Collapse Potential

Moderate (>1%)

No
Planview
Available



OregonGeology

Netarts - Oceanside RFPD Station #62 Oceanside

Till_fir10A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Torsion: Eccentric Stiffness		Building On Hill or Sloped Site	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
SW	Falling Hazard	W	Building Name
			
W	Building Name	W	Building Name
			
NE	Vertical Irregularity Primary		



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries