

Rockaway Police Dept

City of Rockaway Beach

Till_pol03A

Building Type Police - City	County Tillamook	
Street 202 N Hwy 101		
City Rockaway Beach	State OR	Zip 97136
Latitude 45.61465	Longitude 123.94337	
Tracking Code RVS in 2006	Inspection Date 9/6/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	0	-0.5	-1	0	0	0	-0.8	0.5
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Rockaway Police Dept

Final RVS Score

Final Type	Final Score
C2	0.5

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rockaway Police Dept

Till_pol03A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1930
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Torsion: Eccentric Stiffness		None	
None		None	
None		None	
Falling Hazards		Poor Conditions	
Other: Ornamental Hazard Over Exit		None	
None		None	
None		None	
			
N	Elevation View	NW	Plan Irregularity Primary
			
W		Building Name	
			
N	Primary Structural Type FORM MARKS	SW	Elevation View NO POUNDING



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries