

# South Prairie Elementary School

Tillamook SD 9

Till\_sch01A

Building Type School	County Tillamook	
Street 6855 S Prairie Rd		
City Tillamook	State OR	Zip 97141
Latitude 45.40752	Longitude 123.81667	
Tracking Code SER & RVS2006	Inspection Date 9/8/2006	



Seismicity Zone: Very High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	2.4	0	-0.8	0	2.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

South Prairie Elementary School

## Final RVS Score

Final Type	Final Score
W2	2.9

## FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

# South Prairie Elementary School

Till\_sch01A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
339	1980	1980	1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
36051	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Very Irregular Changes	
Out of Plane Lateral-Force-Resistance Elements		None	
None		None	
Falling Hazards		Poor Conditions	
Other: Ornamental Hazard Over Exit		None	
None		None	
None		None	
			
SW Vertical Irregularity Primary		S Primary Structural Type	
E Falling Hazard			
			
NE Plan Irregularity Primary		NE Elevation View	
SE Plan Irregularity Secondary			
			
S Field Verified Year Built 1981		SW Plan Irregularity Primary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries