

Nestucca Valley Elementary

Nestucca Valley SD 101J

Till_sch04A

Building Type	County
School	Tillamook
Street	
36925 Hwy 101 S	
City	State Zip
Cloverdale	OR 97112
Latitude	Longitude
45.18819	123.90405
Tracking Code	Inspection Date
SER & RVS2006	9/7/2006



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Nestucca Valley Elementary

Final RVS Score

Final Type	Final Score
W2	0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Nestucca Valley Elementary

Till_sch04A

Enrollment 222	Year Built (Field Verified) 1950	Year Built (Alt. Source) 1950	Est. Decade Built 1950
Total Area (square ft) 32073	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes None None	
Falling Hazards Unreinforced Chimneys Other: Ornamental Hazard Over Exit None		Poor Conditions None None None	
 N Building Name		 NW Plan Irregularity Primary	
 N Elevation View		 SW Vertical Irregularity Primary	
 N Falling Hazard		 E Elevation View	
 S Falling Hazard		 S Elevation View	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries