

Garibaldi Elementary School

Till_sch05A

Neah-Kah-Nie SD 56

Building Type		County	
School		Tillamook	
Street			
603 Cypress St			
City	State	Zip	
Garibaldi	OR	97118	
Latitude		Longitude	
45.56186		123.91409	
Tracking Code		Inspection Date	
SER & RVS2006		9/11/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	0	-1	0	0	-0.8	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Garibaldi Elementary School

Final RVS Score

Final Type

Final Score

W2

0

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries


Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
129		1927	1920
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
28400	2	No	Yes

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Steps in Elevation View: 2 to 3 Changes
Out of Plane Lateral-Force-Resistance Elements	Building On Hill or Sloped Site
Reentrant Corners: Other (Adjacent Build/Entity	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



SE Vertical Irregularity Secondary



E Number of Stories



NE Vertical Irregularity Primary



NW Plan Irregularity Primary

Garibaldi Elementary School

Till_sch05B

Neah-Kah-Nie SD 56

Building Type		County	
School		Tillamook	
Street			
603 Cypress St			
City	State	Zip	
Garibaldi	OR	97118	
Latitude		Longitude	
45.56178		123.91484	
Tracking Code		Inspection Date	
SER & RVS2006		9/11/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	0	0	0	0	-0.8	0	1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Garibaldi Elementary School

Final RVS Score

Final Type

Final Score

W2

1

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
129		1927	1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
28400	1	No	Yes

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Steps in Elevation View: 2 to 3 Changes
None	Building On Hill or Sloped Site
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



SE Vertical Irregularity Primary



NW Elevation View

