

# Neah-Kah-Nie Jr/Sr High School

Neah-Kah-Nie SD 56

Till\_sch07A

Building Type School	County Tillamook	
Street 24705 Hwy 101 N		
City Rockaway Beach	State OR	Zip 97136
Latitude 45.63884	Longitude 123.93962	
Tracking Code SER & RVS2006	Inspection Date 9/6/2006	



Seismicity Zone: Very High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	0	-0.8	0	0.5
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Neah-Kah-Nie Jr/Sr High School

## Final RVS Score

Final Type	Final Score
W2	0.5

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Neah-Kah-Nie Jr/Sr High School

Till\_sch07A

Enrollment 377	Year Built (Field Verified) 1952	Year Built (Alt. Source) 1952	Est. Decade Built 1950
Total Area (square ft) 95000	Number of Stories 2	Basement	Pounding Potential Yes
Plan Irregularities Reentrant Corners:Other (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity) Building On Hill or Sloped Site None	
Falling Hazards None None None		Poor Conditions None None None	
			
SW Building Name cmu @ entry	W Vertical Irregularity Secondary	NW Vertical Irregularity Primary conn to f	
			
W Elevation View	N General Site conn to d and f	E Elevation View	
			
E Vertical Irregularity Secondary conn to d	E Vertical Irregularity Secondary conn to b		



# OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Neah-Kah-Nie Jr/Sr High School

Till\_sch07B

Neah-Kah-Nie SD 56

Building Type	County
School	Tillamook
Street	
24705 Hwy 101 N	
City	State Zip
Rockaway Beach	OR 97136
Latitude	Longitude
45.63846	123.93965
Tracking Code	Inspection Date
SER & RVS2006	9/6/2006



Seismicity Zone: Very High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	0	-0.8	0	0.5
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Neah-Kah-Nie Jr/Sr High School

## Final RVS Score

Final Type	Final Score
W2	0.5

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

# Neah-Kah-Nie Jr/Sr High School

Till\_sch07B

Enrollment 377	Year Built (Field Verified) 1952	Year Built (Alt. Source) 1952	Est. Decade Built 1970
Total Area (square ft) 95000	Number of Stories 2	Basement No	Pounding Potential Yes
Plan Irregularities Reentrant Corners:Other (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity) Building On Hill or Sloped Site None	
Falling Hazards None None None		Poor Conditions None None None	
 NE Elevation View		 E Vertical Irregularity Secondary conn to a	
		 NE Vertical Irregularity Primary conn to c	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Neah-Kah-Nie Jr/Sr High School

Till\_sch07C

Neah-Kah-Nie SD 56

Building Type	County
School	Tillamook
Street	
24705 Hwy 101 N	
City	State Zip
Rockaway Beach	OR 97136
Latitude	Longitude
45.63816	123.93933
Tracking Code	Inspection Date
SER & RVS2006	9/6/2006



Seismicity Zone: Very High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Neah-Kah-Nie Jr/Sr High School

## Final RVS Score

Final Type	Final Score
W2	0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Neah-Kah-Nie Jr/Sr High School

Till\_sch07C

Enrollment 377	Year Built (Field Verified) 1952	Year Built (Alt. Source) 1970	Est. Decade Built 1970
Total Area (square ft) 95000	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Single Change	
Reentrant Corners: Other (Adjacent Build/Entity)		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
S Primary Structural Type nails in new siding		SW Plan Irregularity Primary	
		SW Plan Irregularity Secondary conn to b	
			
N Elevation View conn to b		NE Vertical Irregularity Secondary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Neah-Kah-Nie Jr/Sr High School

Till\_sch07D

Neah-Kah-Nie SD 56

Building Type	County
School	Tillamook
Street	
24705 Hwy 101 N	
City	State Zip
Rockaway Beach	OR 97136
Latitude	Longitude
45.63913	123.93919
Tracking Code	Inspection Date
SER & RVS2006	9/6/2006



Seismicity Zone: Very High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	0	0	0	0	-0.6	0	1.2
Secondary	C1	2.5	-1.5	0	0	0	0	-0.6	0	0.4
Tertiary	C3	1.6	-1	0	0	0	0	-0.4	0	0.2

Neah-Kah-Nie Jr/Sr High School

## Final RVS Score

Final Type	Final Score
C3	0.2

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

# Neah-Kah-Nie Jr/Sr High School

Till\_sch07D

Enrollment 377	Year Built (Field Verified) 1952	Year Built (Alt. Source) 1952	Est. Decade Built 1950
Total Area (square ft) 95000	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities Reentrant Corners:Other (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity) None None	
Falling Hazards None None None		Poor Conditions None None None	
			
NE Plan Irregularity Primary		SE Elevation View	
		S Primary Structural Type cmu-shape patterns in skim coat between cols	
		S Primary Structural Type more cmu patterns	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Neah-Kah-Nie Jr/Sr High School

Till\_sch07E

Neah-Kah-Nie SD 56

Building Type	County
School	Tillamook
Street	
24705 Hwy 101 N	
City	State Zip
Rockaway Beach	OR 97136
Latitude	Longitude
45.63943	123.93909
Tracking Code	Inspection Date
SER & RVS2006	9/6/2006

Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	0	-0.6	0	0.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Neah-Kah-Nie Jr/Sr High School

Final RVS Score

Final Type	Final Score
RM1	0.7

FEMA-154 Collapse Potential

High (>10%)
-------------



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	0	-0.6	0	0.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Neah-Kah-Nie Jr/Sr High School

Final RVS Score

Final Type	Final Score
RM1	0.7

FEMA-154 Collapse Potential

High (>10%)
-------------



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Neah-Kah-Nie Jr/Sr High School

Till\_sch07E

Enrollment 377	Year Built (Field Verified) 1952	Year Built (Alt. Source) 1952	Est. Decade Built 1970
Total Area (square ft) 95000	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes	
Reentrant Corners: Other (Adjacent Build/Entity)		Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)	
None		None	
Falling Hazards		Poor Conditions	
None		Cracks	
None		None	
None		None	
			
W	Primary Structural Type	W	Poor Condition
			
N	Poor Condition		
			
NE	Elevation View	E	Plan Irregularity Primary
			
E	Plan Irregularity Secondary		



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Neah-Kah-Nie Jr/Sr High School

Neah-Kah-Nie SD 56

Till\_sch07F

Building Type	County
School	Tillamook
Street	
24705 Hwy 101 N	
City	State Zip
Rockaway Beach	OR 97136
Latitude	Longitude
45.63918	123.93971
Tracking Code	Inspection Date
SER & RVS2006	9/6/2006



Seismicity Zone: Very High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	0	-0.8	0	0.5
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Neah-Kah-Nie Jr/Sr High School

## Final RVS Score

Final Type	Final Score
W2	0.5

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Neah-Kah-Nie Jr/Sr High School

Till\_sch07F

Enrollment 377	Year Built (Field Verified) 1952	Year Built (Alt. Source) 1952	Est. Decade Built 1970
Total Area (square ft) 95000	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: L Shaped		Steps in Elevation View: Single Change	
Reentrant Corners: Other (Adjacent Build/Entity)		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
SW General Site conn to a	N Plan Irregularity Primary	NE Vertical Irregularity Primary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries