

Emigrant Hall

Blue Mountain CC

Umat_coc01A

| | | | |
|--------------------|-------|-----------------|--|
| Building Type | | County | |
| Community_College | | Umatilla | |
| Street | | | |
| 2411 NW Carden Ave | | | |
| City | State | Zip | |
| Pendleton | OR | 97801 | |
| Latitude | | Longitude | |
| 45.67743 | | 118.81475 | |
| Tracking Code | | Inspection Date | |
| Miller 2004-05 | | 3/1/2007 | |

Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary | W2 | 4.8 | -3 | -0.5 | 0 | 1.6 | 0 | 0 | 0 | 2.9 |
| Secondary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Emigrant Hall

Final RVS Score

Final Type


Final Score

W2

2.9

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

| | | | |
|------------------------|-----------------------------|--------------------------|--------------------|
| Enrollment | Year Built (Field Verified) | Year Built (Alt. Source) | Est. Decade Built |
| | 1986 | 1986 | 1980 |
| Total Area (square ft) | Number of Stories | Basement | Pounding Potential |
| 10600 | 1 | Yes | No |

| | |
|---------------------|-------------------------|
| Plan Irregularities | Vertical Irregularities |
| None | Yes: Unknown |
| | |
| | |

| | |
|-----------------|-----------------|
| Falling Hazards | Poor Conditions |
| None | |
| None | |
| | |

