

Helix RFPD 7

Helix RFPD

Umat_fir01A

Building Type Fire - RFPD	County Umatilla	
Street 125 Concord		
City Helix	State OR	Zip 97835
Latitude 45.85036	Longitude 118.65533	
Tracking Code RVS in 2006	Inspection Date 8/4/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S3	3.8	0	0	0	0	-0.6	0	0	3.2
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Helix RFPD 7

Final RVS Score

Final Type	Final Score
S3	3.2

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1986	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
3000	1	No	No
Plan Irregularities		Vertical Irregularities	
None		None	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
SW Elevation View			

