

# Stanfield Fire Dist

City of Stanfield

Umat\_fir02A

Building Type Fire - City	County Umatilla	
Street 280 W Coe		
City Stanfield	State OR	Zip 97875
Latitude 45.78083	Longitude 119.21963	
Tracking Code RVS in 2006	Inspection Date 8/16/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S3	3.8	0	-0.5	0	0	0	-1	0	2.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Stanfield Fire Dist

## Final RVS Score

Final Type	Final Score
S3	2.3

## FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Stanfield Fire Dist

Umat\_fir02A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1979	1990
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
4900	1	No	No
Plan Irregularities		Vertical Irregularities	
Torsion: Eccentric Stiffness		None	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
NW Elevation View			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries