

Milton Freewater RFD

City of Milton-Freewater

Umat_fir03A

Building Type	County	
Fire - City	Umatilla	
Street		
84629 Eastside Rd		
City	State	Zip
Milton-Freewater	OR	97862
Latitude	Longitude	
45.9644	118.37648	
Tracking Code	Inspection Date	
RVS in 2006	8/2/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S3	3.8	0	-0.5	0	0	-0.6	0	0	2.7
Secondary	W1	5.2	-3.5	-0.5	0	1.6	-0.2	0	0	2.6
Tertiary		0	0	0	0	0	0	0	0	0

Milton Freewater RFD

Final RVS Score

Final Type	Final Score
W1	2.6

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Milton Freewater RFD

Umat_fir03A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1983	1983	1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
2220	2	No	No
Plan Irregularities		Vertical Irregularities	
Torsion: Eccentric Stiffness		Steps in Elevation View: Single Change	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
W	Vertical Irregularity Primary	N	Elevation View



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries