

Hermiston Fire & Emergency

Hermiston Fire & Emergency Services District

Umat_fir04A

Building Type		County	
EOC-Public Safety Answering P		Umatilla	
Street			
330 S First			
City	State	Zip	
Hermiston	OR	97838	
Latitude	Longitude		
45.8385	119.29079		
Tracking Code	Inspection Date		
RVS in 2006	8/15/2006		



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Hermiston Fire & Emergency

Final RVS Score

Final Type

Final Score

RM1

0.3

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1974	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
17717	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Steps in Elevation View: 2 to 3 Changes
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



SW Elevation View



W Elevation View



E Elevation View