

Pendleton City Fire

City of Pendleton

Umat_fir06A

Building Type	County
Fire - City	Umatilla
Street	
911 SW Court Ave	
City	State Zip
Pendleton	OR 97801
Latitude	Longitude
45.67024	118.79656
Tracking Code	Inspection Date
RVS in 2006	8/1/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Pendleton City Fire

Final RVS Score

Final Type	Final Score
C2	0.3

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Pendleton City Fire

Umat_fir06A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
10848	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Single Change	
Torsion: Eccentric Stiffness		Steps in Elevation View: Single Change	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
SE	Primary Structural Type	S	Plan Irregularity Primary
		NW Elevation View	
		N Vertical Irregularity Primary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries