

East Umatilla County RFPD

East Umatilla County RFPD

Umat_fir07A

Building Type Fire - RFPD	County Umatilla	
Street 77167 Spring Hollow Rd		
City Adams	State OR	Zip 97810
Latitude 45.76881	Longitude 118.55766	
Tracking Code New Building	Inspection Date 8/2/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S3	3.8	0	0	0	0	-0.6	0	0	3.2
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

East Umatilla County RFPD

Final RVS Score

Final Type	Final Score
S3	3.2

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

East Umatilla County RFPD

Umat_fir07A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1996	1990
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
3000	1	No	No
Plan Irregularities		Vertical Irregularities	
None		None	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
NE Elevation View			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries