

# East Umatilla County RFPD

East Umatilla County RFPD

Umat\_fir08A

Building Type Fire - RFPD	County Umatilla	
Street 57770 Hwy 204		
City Weston	State OR	Zip 97886
Latitude 45.7879	Longitude 118.2525	
Tracking Code New Building	Inspection Date 8/4/2006	



Seismicity Zone: Moderate										
FEMA 154 Rapid Visual Screening Score Card										
	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S3	3.8	0	-0.5	0	0	0	0	0	3.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

East Umatilla County RFPD

Final RVS Score

Final Type	Final Score
S3	3.3

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# East Umatilla County RFPD

Umat\_fir08A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1999	1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
1920	1	No	No
Plan Irregularities		Vertical Irregularities	
Torsion: Eccentric Stiffness		None	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries