

Building Type	County
<input type="text"/>	
Street	
1200 Southgate	
City	State Zip
Pendleton	OR <input type="text"/>
Latitude	Longitude
45.65441	118.81051
Tracking Code	Inspection Date
RVS in 2006	8/1/2006



Seismicity Zone: Moderate										
FEMA 154 Rapid Visual Screening Score Card										
	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary										
Secondary										
Tertiary										

Pendleton City Fire #2

Final RVS Score

Final Type	Final Score
<input type="text"/>	<input type="text"/>

FEMA-154 Collapse Potential

<input type="text"/>

No
Planview
Available



OregonGeology

Pendleton City Fire #2

Umat_fir14A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: T shaped		None	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
S	Elevation View		



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries