

Building Type		County	
EOC-Public Safety Answering P		Umatilla	
Street			
4700 Nw Pioneer Pl			
City	State	Zip	
Pendleton	OR	97801	
Latitude	Longitude		
45.67366	118.84322		
Tracking Code	Inspection Date		
RVS in 2006	8/1/2006		



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C1	3	-2	-0.5	0	0	0	0	0	0.5
Secondary	C2	3.6	-2	-0.5	0	1.6	0	0	0	2.7
Tertiary	S2	3.6	-2	-0.5	0	0	0	0	0	1.1

Umatilla County Sheriff's Dept

## Final RVS Score

Final Type

Final Score

C1

0.5

## FEMA-154 Collapse Potential

High (&gt;10%)



Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1992	1992	1990
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
5500	2	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Building On Hill or Sloped Site
None	Steps in Elevation View: 2 to 3 Changes
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



S Vertical Irregularity Secondary