

OSP

Oregon State Police

Umat_pol05A

Building Type	County
Police - State	Umatilla
Street	
700 Se Emigrant Ave	
City	State Zip
Pendleton	OR 97801
Latitude	Longitude
45.67261	118.7791
Tracking Code	Inspection Date
RVS in 2006	8/1/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	0	-0.5	0	0	0	0	0	3.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

OSP

Final RVS Score

Final Type	Final Score
RM1	3.1

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1963	1963	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
13486	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: L Shaped		None	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
W	Elevation View	E	Plan Irregularity Primary

