

# Milton Freewater Police Dept and OSP

City of Milton-Freewater

Umat\_pol07A

Building Type Police - City	County Umatilla	
Street 722 S Main St		
City Milton-Freewater	State OR	Zip 97862
Latitude 45.92811	Longitude 118.38572	
Tracking Code RVS in 2006	Inspection Date 8/2/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	URM	3.4	-1.5	-0.5	-0.4	0	0	-0.8	0	0.2
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Milton Freewater Police Dept and OSP

Final RVS Score

Final Type	Final Score
URM	0.2

FEMA-154 Collapse Potential

High (>10%)
-------------




OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Milton Freewater Police Dept and OSP

Umat\_pol07A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1910	1910	1910
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
5821	2	Yes	No
Plan Irregularities		Vertical Irregularities	
Out of Plane Lateral-Force-Resistance Elements		Steps in Elevation View: Single Change	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
E	Field Verified Year Built	S	Elevation View
			
W	Seismic Upgrade	W	Elevation View



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries