

Weston Police Dept

City of Weston

Umat_pol08A

Building Type Police-City	County Umatilla	
Street 112 E Main St		
City Weston	State OR	Zip 97886
Latitude 45.81348	Longitude 118.42429	
Tracking Code RVS in 2006	Inspection Date 8/4/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	URM	3.4	-1.5	-0.5	-0.4	0	0	0	0	1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Weston Police Dept

Final RVS Score

Final Type	Final Score
URM	1

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1890	Pre 1900
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
1824	1	Yes	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners:L shaped (Adjacent Build/Entity)		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
None		Soft Story	
None		None	
Falling Hazards		Poor Conditions	
None		Poor Masonry	
None		None	
None		None	
			
N	Elevation View	S	Elevation View
			
E	Poor Condition	NE	Elevation View
			
S Poor Condition			

