


Pilot Rock Police Dept

City of Pilot Rock

Umat_pol09A

Building Type Police - City	County Umatilla	
Street 144 N Alder Pl		
City Pilot Rock	State OR	Zip 97868
Latitude 45.48289	Longitude 118.83293	
Tracking Code RVS in 2006	Inspection Date 8/1/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Pilot Rock Police Dept

Final RVS Score

Final Type	Final Score
RM1	0.3

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Pilot Rock Police Dept

Umat_pol09A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1930	1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
2278	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: L Shaped		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
Reentrant Corners: Other		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
E Elevation View			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries