

# McNary Heights Elementary School

Umat\_sch01A

Umatilla SD 6R

Building Type	County	
School	Umatilla	
Street		
120 Columbia Ave		
City	State	Zip
Umatilla	OR	97882
Latitude	Longitude	
45.91945	119.2952	
Tracking Code	Inspection Date	
RVS in 2006	8/15/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	0	-1.2	0	-0.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

McNary Heights Elementary School

## Final RVS Score

Final Type

Final Score

RM1

-0.1

FEMA-154 Collapse Potential

Very High (100%)

**No  
Planview  
Available**



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# McNary Heights Elementary School

Umat\_sch01A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
606		1975	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
44779	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Steps in Elevation View: Single Change
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



NW Elevation View



NW Elevation View



E Elevation View



SE Elevation View