

Highland Hills Elementary School

Hermiston SD 8

Umat_sch03A

Building Type		County	
School		Umatilla	
Street			
450 Se 10Th St			
City	State	Zip	
Hermiston	OR	97838	
Latitude		Longitude	
45.83662		119.2704	
Tracking Code		Inspection Date	
RVS in 2006		8/16/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	PC1	3.2	0	0	0	0	-0.6	0	0	2.6
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Highland Hills Elementary School

Final RVS Score

Final Type

Final Score

PC1

2.6

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
530	1980	1980	1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
38600	1	No	No

Plan Irregularities	Vertical Irregularities
None	None
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



S Elevation View



S Primary Structural Type



E Field Verified Year Built

Highland Hills Elementary School

Hermiston SD 8

Umat_sch03B

Building Type		County	
School		Umatilla	
Street			
450 Se 10Th St			
City	State	Zip	
Hermiston	OR	97838	
Latitude		Longitude	
45.83696		119.27041	
Tracking Code		Inspection Date	
RVS in 2006		8/16/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	PC1	3.2	0	0	0	0	-0.6	0	0	2.6
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Highland Hills Elementary School

Final RVS Score

Final Type

Final Score

PC1

2.6

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
530		1980	1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
38600	1	No	No

Plan Irregularities	Vertical Irregularities
None	None
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



NE Elevation View

Highland Hills Elementary School

Hermiston SD 8

Umat_sch03C

Building Type		County	
School		Umatilla	
Street			
450 Se 10Th St			
City	State	Zip	
Hermiston	OR	97838	
Latitude		Longitude	
45.83698		119.27111	
Tracking Code		Inspection Date	
RVS in 2006		8/16/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	PC1	3.2	0	-0.5	0	0	-0.6	0	0	2.1
Secondary	RM1	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Tertiary		0	0	0	0	0	0	0	0	0

Highland Hills Elementary School

Final RVS Score

Final Type

Final Score

RM1

0.3

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
530		1980	1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
38600	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: L Shaped	Steps in Elevation View: Single Change (Adjacent Building/Entity)
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



NW Elevation View