

# Sunset Elementary School

Umat\_sch05A

Hermiston SD 8

Building Type		County	
School		Umatilla	
Street			
300 E Catherine Ave			
City	State	Zip	
Hermiston	OR	97838	
Latitude		Longitude	
45.84421		119.28714	
Tracking Code		Inspection Date	
RVS in 2006		8/16/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Secondary	PC1	3.2	0	-0.5	0	0	-0.6	0	0	2.1
Tertiary		0	0	0	0	0	0	0	0	0

Sunset Elementary School

## Final RVS Score

Final Type

Final Score

C2

0.3

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Sunset Elementary School

Umat\_sch05A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
457	1957	1957	1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
80196	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Steps in Elevation View: Single Change
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



N Elevation View



W Elevation View



E Elevation View



E Field Verified Year Built

# Sunset Elementary School

Hermiston SD 8

Umat\_sch05B

Building Type		County	
School		Umatilla	
Street			
300 E Catherine Ave			
City	State	Zip	
Hermiston	OR	97838	
Latitude		Longitude	
45.84437		119.28786	
Tracking Code		Inspection Date	
RVS in 2006		8/16/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	0	0	0	0	-0.8	0	0	2.8
Secondary	PC1	3.2	0	0	0	0	-0.6	0	0	2.6
Tertiary		0	0	0	0	0	0	0	0	0

Sunset Elementary School

## Final RVS Score

Final Type

Final Score

PC1

2.6

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
457		1957	1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No

Plan Irregularities	Vertical Irregularities
None	None
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



S Elevation View



# Sunset Elementary School

Umat\_sch05C

Hermiston SD 8

Building Type		County	
School		Umatilla	
Street			
300 E Catherine Ave			
City	State	Zip	
Hermiston	OR	97838	
Latitude		Longitude	
45.84429		119.28648	
Tracking Code		Inspection Date	
RVS in 2006		8/16/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	0	0	0	0	-0.8	0	0	2.8
Secondary	PC1	3.2	0	0	0	0	-0.6	0	0	2.6
Tertiary		0	0	0	0	0	0	0	0	0

Sunset Elementary School

## Final RVS Score

Final Type

Final Score

PC1

2.6

FEMA-154 Collapse Potential

Low (<1%)




OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
457		1957	1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No

Plan Irregularities	Vertical Irregularities
None	None
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



S Elevation View



# Sunset Elementary School

Hermiston SD 8

Umat\_sch05D

Building Type		County	
School		Umatilla	
Street			
300 E Catherine Ave			
City	State	Zip	
Hermiston	OR	97838	
Latitude		Longitude	
45.84429		119.28593	
Tracking Code		Inspection Date	
RVS in 2006		8/16/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	0	0	0	0	-0.8	0	0	2.8
Secondary	PC1	3.2	0	0	0	0	-0.6	0	0	2.6
Tertiary		0	0	0	0	0	0	0	0	0

Sunset Elementary School

## Final RVS Score

Final Type

Final Score

PC1

2.6

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
457		1957	1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No

Plan Irregularities	Vertical Irregularities
None	None
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None