

Sunridge Middle School

Pendleton SD 16

Umat_sch12A

Building Type School	County Umatilla	
Street 700 Sw Runnion Ave		
City Pendleton	State OR	Zip 97801
Latitude 45.65053	Longitude 118.78714	
Tracking Code RVS in 2006	Inspection Date 8/15/2006	



Seismicity Zone: Moderate										
FEMA 154 Rapid Visual Screening Score Card										
	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S2	3.6	-2	-0.5	0	0	0	0	0	1.1
Secondary	S1	3.6	-2	-0.5	0	0	0	0	0	1.1
Tertiary	RM1	3.6	-2	-0.5	0	0	0	0	0	1.1

Sunridge Middle School

Final RVS Score

Final Type	Final Score
S2	1.1

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Sunridge Middle School

Umat_sch12A

Enrollment 807	Year Built (Field Verified) 1981	Year Built (Alt. Source) 1981	Est. Decade Built 1980
Total Area (square ft) 181382	Number of Stories 2	Basement	Pounding Potential Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other None None		Steps in Elevation View: Very Irregular Changes Building On Hill or Sloped Site None	
Falling Hazards		Poor Conditions	
None None None		None None None	
			
E	Elevation View	N	Elevation View
			
N	Elevation View	N	Elevation View
			
E	Elevation View	N	Elevation View



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries