

Pendleton High School

Pendleton SD 16

Umat_sch13A

Building Type		County	
School		Umatilla	
Street			
1800 Nw Carden Ave			
City	State	Zip	
Pendleton	OR	97801	
Latitude		Longitude	
45.67518		118.80457	
Tracking Code		Inspection Date	
RVS in 2006		8/1/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM2	3.4	-1.5	-0.5	0	0	-0.6	0	0	0.8
Secondary	RM1	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Tertiary		0	0	0	0	0	0	0	0	0

Pendleton High School

Final RVS Score

Final Type

Final Score

RM1

0.3

FEMA-154 Collapse Potential

High (>10%)



Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
1006		1968	1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
219962	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners:L shaped (Adjacent Build/Entity)	Steps in Elevation View: Single Change (Adjacent Building/Entity)
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



S Field Verified Year Built



W Elevation View



W Primary Structural Type



NW Elevation View



NW Primary Structural Type



E Elevation View



Pendleton High School

Pendleton SD 16

Umat_sch13B

Building Type		County	
School		Umatilla	
Street			
1800 Nw Carden Ave			
City	State	Zip	
Pendleton	OR	97801	
Latitude		Longitude	
45.67489		118.80456	
Tracking Code		Inspection Date	
RVS in 2006		8/1/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Secondary	C1	3	-2	-0.5	0	0	-0.6	0	0	-0.1
Tertiary		0	0	0	0	0	0	0	0	0

Pendleton High School

Final RVS Score

Final Type

Final Score

C1

-0.1

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
1006		1968	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
219962	1	Yes	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners:T shaped (Adjacent Build/Entity)	Steps in Elevation View: Single Change (Adjacent Building/Entity)
None	Building On Hill or Sloped Site
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



S Primary Structural Type



SE Vertical Irregularity Secondary



Pendleton High School

Pendleton SD 16

Umat_sch13C

Building Type		County	
School		Umatilla	
Street			
1800 Nw Carden Ave			
City	State	Zip	
Pendleton	OR	97801	
Latitude		Longitude	
45.67589		118.80476	
Tracking Code		Inspection Date	
RVS in 2006		8/1/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	-2	0	0	0	-0.8	0	0	0.8
Secondary	RM1	3.6	-2	0	0	0	-0.8	0	0	0.8
Tertiary		0	0	0	0	0	0	0	0	0

Pendleton High School

Final RVS Score

Final Type

Final Score

C2

0.8

FEMA-154 Collapse Potential

High (>10%)




OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
1006		1968	1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
219962	1	No	No

Plan Irregularities	Vertical Irregularities
None	Building On Hill or Sloped Site
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



S Primary Structural Type

W Vertical Irregularity Primary



Pendleton High School

Umat_sch13D

Pendleton SD 16

Building Type		County	
School		Umatilla	
Street			
1800 Nw Carden Ave			
City	State	Zip	
Pendleton	OR	97801	
Latitude		Longitude	
45.67564		118.80593	
Tracking Code		Inspection Date	
RVS in 2006		8/1/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Pendleton High School

Final RVS Score

Final Type

Final Score

RM1

0.3

FEMA-154 Collapse Potential

High (>10%)



Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
1006		1968	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
219962	1	Yes	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners:T shaped (Adjacent Build/Entity)	Steps in Elevation View: Single Change (Adjacent Building/Entity)
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



NE Elevation View



Pendleton High School

Pendleton SD 16

Umat_sch13E

Building Type		County	
School		Umatilla	
Street			
1800 Nw Carden Ave			
City		State	Zip
Pendleton		OR	97801
Latitude		Longitude	
45.67544		118.80504	
Tracking Code		Inspection Date	
RVS in 2006		8/1/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Pendleton High School

Final RVS Score

Final Type

Final Score

RM1

0.3

FEMA-154 Collapse Potential

High (>10%)



Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
1006		1968	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
219962	1	Yes	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Steps in Elevation View: Single Change (Adjacent Building/Entity)
None	Building On Hill or Sloped Site
None	Steps in Elevation View: Single Change

Falling Hazards	Poor Conditions
None	None
None	None
None	None



SE General Site

