

Central Middle School

Milton-Freewater Unified SD 7

Umat_sch14A

Building Type		County	
School		Umatilla	
Street			
306 Sw 2nd Ave			
City		State	Zip
Milton-Freewater		OR	97862
Latitude		Longitude	
45.93353		118.39173	
Tracking Code		Inspection Date	
RVS in 2006		8/2/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	URM	3.4	0	-0.5	-0.4	0	0	-0.8	0	1.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Central Middle School

Final RVS Score

Final Type

Final Score

URM

1.7

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
450		1909	1900
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
61202	2	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: T shaped	None
None	None
None	None

Falling Hazards	Poor Conditions
Unreinforced Chimneys	None
None	None
None	None



Central Middle School

Milton-Freewater Unified SD 7

Umat_sch14B

Building Type		County	
School		Umatilla	
Street			
306 Sw 2nd Ave			
City		State	Zip
Milton-Freewater		OR	97862
Latitude		Longitude	
45.93327		118.39162	
Tracking Code		Inspection Date	
RVS in 2006		8/2/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	-3	-0.5	0	0	0	-1.2	0	0.1
Secondary	C2	3.6	-2	-0.5	0	0	0	-1.2	0	-0.1
Tertiary	RM1	3.6	-2	-0.5	0	0	0	-1.2	0	-0.1

Central Middle School

Final RVS Score

Final Type

Final Score

C2

-0.1

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
450		1909	1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
61202	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Steps in Elevation View: Single Change
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



Central Middle School

Milton-Freewater Unified SD 7

Umat_sch14C

Building Type		County	
School		Umatilla	
Street			
306 Sw 2nd Ave			
City		State	Zip
Milton-Freewater		OR	97862
Latitude		Longitude	
45.93333		118.39092	
Tracking Code		Inspection Date	
RVS in 2006		8/2/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	0	-0.5	0	0	0	-1.2	0	3.1
Secondary	C2	3.6	0	-0.5	0	0	0	-1.2	0	1.9
Tertiary	RM1	3.6	0	-0.5	0	0	0	-1.2	0	1.9

Central Middle School

Final RVS Score

Final Type

Final Score

C2

1.9

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
450		1909	1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
61202	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: L Shaped	None
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



SE Plan Irregularity Primary



SE Elevation View



SW Elevation View



N Elevation View

Central Middle School

Milton-Freewater Unified SD 7

Umat_sch14D

Building Type		County	
School		Umatilla	
Street			
306 Sw 2nd Ave			
City	State	Zip	
Milton-Freewater	OR	97862	
Latitude		Longitude	
45.93338		118.39218	
Tracking Code		Inspection Date	
RVS in 2006		8/2/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	0	-1.2	0	-0.1
Secondary	PC1	3.2	0	-0.5	0	0	0	-1	0	1.7
Tertiary	C2	3.6	-2	-0.5	0	0	0	-1.2	0	-0.1

Central Middle School

Final RVS Score

Final Type

Final Score

RM1

-0.1

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
450		1909	1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
61202	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: L Shaped	Steps in Elevation View: Single Change
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



S Plan Irregularity Primary



NE Elevation View



E Elevation View