

# Stanfield Elementary School

Stanfield SD 61

Umat\_sch17A

Building Type School	County Umatilla	
Street 1120 N Main St		
City Stanfield	State OR	Zip 97875
Latitude 45.79036	Longitude 119.22669	
Tracking Code New Building	Inspection Date 9/15/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Stanfield Elementary School

## Final RVS Score

Final Type      Final Score

## FEMA-154 Collapse Potential

Low (<1%)

No  
Planview  
Available



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Stanfield Elementary School

Umat\_sch17A

Enrollment 319	Year Built (Field Verified) 2001	Year Built (Alt. Source) 2001	Est. Decade Built
Total Area (square ft) 46000	Number of Stories	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Falling Hazards		Poor Conditions	