

Stanfield Secondary School

Stanfield SD 61

Umat_sch18A

Building Type		County	
School		Umatilla	
Street			
1120 N Main St			
City	State	Zip	
Stanfield	OR	97875	
Latitude		Longitude	
45.78987		119.22419	
Tracking Code		Inspection Date	
RVS in 2006		8/16/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	PC1	3.2	0	-0.5	0	0	0	0	0	2.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Stanfield Secondary School

Final RVS Score

Final Type

Final Score

PC1

2.7

FEMA-154 Collapse Potential

Low (<1%)




OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
237		1979	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
77984	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: U shaped	Steps in Elevation View: 2 to 3 Changes
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



E Elevation View



SE Elevation View



SW Elevation View



NW Elevation View