

Desert View Elementary School

Hermiston SD 8

Umat_sch20A

Building Type	County	
School	Umatilla	
Street		
1225 Sw 9th		
City	State	Zip
Hermiston	OR	97838
Latitude	Longitude	
45.83041	119.30464	
Tracking Code	Inspection Date	
New Building	9/15/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Desert View Elementary School

Final RVS Score

Final Type

Final Score

FEMA-154 Collapse Potential

Low (<1%)

No Planview Available



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
443		2001	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
45441		No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions