

Pilot Rock Elementary School

Pilot Rock SD 2

Umat_sch21A

| | | |
|------------------------------|-----------------------------|--------------|
| Building Type School | County Umatilla | |
| Street Vern McGowan Dr | | |
| City Pilot Rock | State OR | Zip 97868 |
| Latitude 45.47954 | Longitude 118.83345 | |
| Tracking Code RVS in 2006 | Inspection Date 8/1/2006 | |



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary | RM1 | 3.6 | 0 | -0.5 | 0 | 0 | 0 | 0 | 0 | 3.1 |
| Secondary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Pilot Rock Elementary School

Final RVS Score

| Final Type | Final Score |
|------------|-------------|
| RM1 | 3.1 |

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Pilot Rock Elementary School

Umat_sch21A

| | | | |
|--|-------------------------------------|---|---------------------------|
| Enrollment 209 | Year Built (Field Verified) 1948 | Year Built (Alt. Source) 1948 | Est. Decade Built 1940 |
| Total Area (square ft) 39385 | Number of Stories 1 | Basement | Pounding Potential No |
| Plan Irregularities Reentrant Corners: L Shaped None None | | Vertical Irregularities None None None | |
| Falling Hazards None None None | | Poor Conditions None None None | |
|  SW Elevation View attach w/building b | |  N Elevation View | |



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Pilot Rock Elementary School

Pilot Rock SD 2

Umat_sch21B

| | |
|-----------------|-----------------|
| Building Type | County |
| School | Umatilla |
| Street | |
| Vern McGowan Dr | |
| City | State Zip |
| Pilot Rock | OR 97868 |
| Latitude | Longitude |
| 45.47923 | 118.8332 |
| Tracking Code | Inspection Date |
| RVS in 2006 | 8/1/2006 |



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary | RM1 | 3.6 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 3.6 |
| Secondary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Pilot Rock Elementary School

Final RVS Score

| | |
|------------|-------------|
| Final Type | Final Score |
| RM1 | 3.6 |

FEMA-154 Collapse Potential

| |
|-----------|
| Low (<1%) |
|-----------|



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Pilot Rock Elementary School

Umat_sch21B

| | | | |
|--|-------------------------------------|---|---------------------------|
| Enrollment 209 | Year Built (Field Verified) 1948 | Year Built (Alt. Source) 1948 | Est. Decade Built 1950 |
| Total Area (square ft) 39385 | Number of Stories 1 | Basement | Pounding Potential No |
| Plan Irregularities None None None | | Vertical Irregularities None None None | |
| Falling Hazards None None None | | Poor Conditions None None None | |
|  E Elevation View | | | |



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Pilot Rock Elementary School

Pilot Rock SD 2

Umat_sch21C

| | | |
|------------------------------|-----------------------------|--------------|
| Building Type School | County Umatilla | |
| Street Vern McGowan Dr | | |
| City Pilot Rock | State OR | Zip 97868 |
| Latitude 45.47918 | Longitude 118.83375 | |
| Tracking Code RVS in 2006 | Inspection Date 8/1/2006 | |



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary | C2 | 3.6 | -2 | -0.5 | 0 | 0 | 0 | 0 | 0 | 1.1 |
| Secondary | W2 | 4.8 | -3 | -0.5 | 0 | 0 | 0 | 0 | 0 | 1.3 |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Pilot Rock Elementary School

Final RVS Score

| Final Type | Final Score |
|------------|-------------|
| C2 | 1.1 |

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Pilot Rock Elementary School

Umat_sch21C

| | | | |
|---|-------------------------------------|--|---------------------------|
| Enrollment 209 | Year Built (Field Verified) 1948 | Year Built (Alt. Source) 1948 | Est. Decade Built 1960 |
| Total Area (square ft) 39385 | Number of Stories 1 | Basement | Pounding Potential No |
| Plan Irregularities Reentrant Corners: L Shaped None None | | Vertical Irregularities Steps in Elevation View: Single Change (Adjacent Building/Entity) None None | |
| Falling Hazards None None None | | Poor Conditions None None None | |
|  N Vertical Irregularity Primary | | | |



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Pilot Rock Elementary School

Pilot Rock SD 2

Umat_sch21D

| | | |
|------------------------------|-----------------------------|--------------|
| Building Type School | County Umatilla | |
| Street Vern McGowan Dr | | |
| City Pilot Rock | State OR | Zip 97868 |
| Latitude 45.47915 | Longitude 118.83409 | |
| Tracking Code RVS in 2006 | Inspection Date 8/1/2006 | |



Seismicity Zone: Moderate

| FEMA 154 Rapid Visual Screening Score Card | | | | | | | | | | |
|--|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
| Primary | C2 | 3.6 | -2 | -0.5 | 0 | 0 | 0 | 0 | 0 | 1.1 |
| Secondary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Pilot Rock Elementary School

Final RVS Score

| | |
|------------------|--------------------|
| Final Type C2 | Final Score 1.1 |
|------------------|--------------------|

FEMA-154 Collapse Potential

| |
|----------------|
| Moderate (>1%) |
|----------------|



OregonGeology

Pilot Rock Elementary School

Umat_sch21D

| | | | |
|--|-------------------------------------|--|---------------------------|
| Enrollment 209 | Year Built (Field Verified) 1948 | Year Built (Alt. Source) 1948 | Est. Decade Built 1960 |
| Total Area (square ft) 39385 | Number of Stories 1 | Basement | Pounding Potential No |
| Plan Irregularities Reentrant Corners:L shaped (Adjacent Build/Entity) Reentrant Corners: T shaped None | | Vertical Irregularities Steps in Elevation View: Single Change (Adjacent Building/Entity) Steps in Elevation View: Single Change None | |
| Falling Hazards None None None | | Poor Conditions None None None | |
|  S Elevation View | | | |



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries