

Weston-McEwen High School

Athena-Weston SD 29RJ

Umat_sch23A

Building Type	County
School	Umatilla
Street	
540 E Main St	
City	State Zip
Athena	OR 97813
Latitude	Longitude
45.81112	118.48595
Tracking Code	Inspection Date
RVS in 2006	8/4/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Secondary	URM	3.4	-1.5	-0.5	0	0	-0.4	0	0	1
Tertiary		0	0	0	0	0	0	0	0	0

Weston-McEwen High School

Final RVS Score

Final Type	Final Score
C2	0.3

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Weston-McEwen High School

Umat_sch23A

Enrollment 235	Year Built (Field Verified) 1949	Year Built (Alt. Source) 1940	Est. Decade Built 1940
Total Area (square ft) 39359	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities Steps in Elevation View: Single Change Steps in Elevation View: Single Change (Adjacent Building/Entity) None	
Falling Hazards Unreinforced Chimneys None None		Poor Conditions None None None	
 SE Elevation View		 SW Falling Hazard	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
 Oregon Department of Geology and Mineral Industries

Weston-McEwen High School

Athena-Weston SD 29RJ

Umat_sch23B

Building Type	County
School	Umatilla
Street	
540 E Main St	
City	State Zip
Athena	OR 97813
Latitude	Longitude
45.81065	118.48594
Tracking Code	Inspection Date
RVS in 2006	8/4/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Weston-McEwen High School

Final RVS Score

Final Type	Final Score
C2	0.3

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Weston-McEwen High School

Umat_sch23B

Enrollment 235	Year Built (Field Verified) 1949	Year Built (Alt. Source) 1940	Est. Decade Built 1940
Total Area (square ft)	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities Steps in Elevation View: Single Change (Adjacent Building/Entity) Steps in Elevation View: 2 to 3 Changes None	
Falling Hazards None None None		Poor Conditions None None None	
 S Primary Structural Type		 SE Elevation View	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Weston-McEwen High School

Athena-Weston SD 29RJ

Umat_sch23C

Building Type School	County Umatilla	
Street 540 E Main St		
City Athena	State OR	Zip 97813
Latitude 45.81087	Longitude 118.48636	
Tracking Code RVS in 2006	Inspection Date 8/4/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Weston-McEwen High School

Final RVS Score

Final Type	Final Score
RM1	0.3

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Enrollment 235	Year Built (Field Verified) 1949	Year Built (Alt. Source) 1960	Est. Decade Built
Total Area (square ft)	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: T shaped None None		Vertical Irregularities Steps in Elevation View: Single Change None None	
Falling Hazards None None None		Poor Conditions None None None	