

# Pilot Rock High School

Pilot Rock SD 2

Umat\_sch26A

Building Type	County
School	Umatilla
Street	
101 NE Cherry	
City	State Zip
Pilot Rock	OR 97868
Latitude	Longitude
45.48271	118.83106
Tracking Code	Inspection Date
RVS in 2006	8/1/2006



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	URM	3.4	-1.5	-0.5	-0.4	0	0	0	0	1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Pilot Rock High School

## Final RVS Score

Final Type	Final Score
URM	1

## FEMA-154 Collapse Potential

High (>10%)



OregonGeology

# Pilot Rock High School

Umat\_sch26A

Enrollment 206	Year Built (Field Verified) 1919	Year Built (Alt. Source) 1955	Est. Decade Built 1910
Total Area (square ft) 61073	Number of Stories 2	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners:Other (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity) None None	
Falling Hazards None None None		Poor Conditions None None None	
 W Field Verified Year Built		 S Plan Irregularity Primary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Pilot Rock High School

Pilot Rock SD 2

Umat\_sch26B

Building Type	County
School	Umatilla
Street	
101 NE Cherry	
City	State Zip
Pilot Rock	OR 97868
Latitude	Longitude
45.48275	118.83086
Tracking Code	Inspection Date
RVS in 2006	8/1/2006



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	-2	-0.5	-0.4	0	0	0	0	0.7
Secondary	C1	3	-2	-0.5	0	0	0	0	0	0.5
Tertiary	URM	3.4	-1.5	-0.5	-0.4	0	0	0	0	1

Pilot Rock High School

## Final RVS Score

Final Type	Final Score
C1	0.5

## FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Pilot Rock High School

Umat\_sch26B

Enrollment 206	Year Built (Field Verified) 1955	Year Built (Alt. Source) 1955	Est. Decade Built 1920
Total Area (square ft)	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners:T shaped (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity) None None	
Falling Hazards None None None		Poor Conditions None None None	
			
W Primary Structural Type note corbeling on columns		W Primary Structural Type double wythe	
		E Elevation View 	
		NE Elevation View	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Pilot Rock High School

Pilot Rock SD 2

Umat\_sch26C

Building Type School	County Umatilla	
Street 101 NE Cherry		
City Pilot Rock	State OR	Zip 97868
Latitude 45.48266	Longitude 118.83066	
Tracking Code RVS in 2006	Inspection Date 8/1/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	0	0	0	1.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Pilot Rock High School

## Final RVS Score

Final Type	Final Score
RM1	1.1

## FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

# Pilot Rock High School

Umat\_sch26C

Enrollment 206	Year Built (Field Verified) 1955	Year Built (Alt. Source) 1955	Est. Decade Built 1950
Total Area (square ft)	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners:T shaped (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: Single Change (Adjacent Building/Entity) None None	
Falling Hazards None None None		Poor Conditions None None None	
 W Plan Irregularity Primary			

# Pilot Rock High School

Pilot Rock SD 2

Umat\_sch26D

Building Type School	County Umatilla	
Street 101 NE Cherry		
City Pilot Rock	State OR	Zip 97868
Latitude 45.48225	Longitude 118.83075	
Tracking Code RVS in 2006	Inspection Date 8/1/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	0	0	0	1.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Pilot Rock High School

## Final RVS Score

Final Type	Final Score
RM1	1.1

## FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

# Pilot Rock High School

Umat\_sch26D

Enrollment 206	Year Built (Field Verified) 1955	Year Built (Alt. Source) 1960	Est. Decade Built 1960
Total Area (square ft)	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners:T shaped (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity) None None	
Falling Hazards None None None		Poor Conditions None None None	
			
E Elevation View		S Elevation View	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Pilot Rock High School

Pilot Rock SD 2

Umat\_sch26E

Building Type	County
School	Umatilla
Street	
101 NE Cherry	
City	State Zip
Pilot Rock	OR 97868
Latitude	Longitude
45.48223	118.83145
Tracking Code	Inspection Date
RVS in 2006	8/1/2006



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	-2	-0.5	0	0	0	0	0	1.1
Secondary	RM1	3.6	-2	-0.5	0	0	0	0	0	1.1
Tertiary		0	0	0	0	0	0	0	0	0

Pilot Rock High School

### Final RVS Score

Final Type	Final Score
C2	1.1

### FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Pilot Rock High School

Umat\_sch26E

Enrollment 206	Year Built (Field Verified) 1955	Year Built (Alt. Source) 1955	Est. Decade Built 1950
Total Area (square ft)	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: Other		Vertical Irregularities Steps in Elevation View: Single Change	
Reentrant Corners: Other		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
None		Building On Hill or Sloped Site	
Falling Hazards None		Poor Conditions None	
None		None	
None		None	
			
W Elevation View		NW Elevation View	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries