

# West Hills Intermediate

Pendleton SD 16

Umat\_sch28A

Building Type	County
School	Umatilla
Street	
1700 NW 15th Dr	
City	State Zip
Pendleton	OR 97801
Latitude	Longitude
45.67736	118.80599
Tracking Code	Inspection Date
RVS in 2006	8/15/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

West Hills Intermediate

Final RVS Score

Final Type	Final Score
RM1	0.3

FEMA-154 Collapse Potential

High (>10%)
-------------



OregonGeology

# West Hills Intermediate

Umat\_sch28A

Enrollment 182	Year Built (Field Verified) 1958	Year Built (Alt. Source) 1958	Est. Decade Built 1950
Total Area (square ft) 21259	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes Building On Hill or Sloped Site None	
Falling Hazards None None None		Poor Conditions None None None	
			
SE Elevation View		SE Elevation View	
			
S Elevation View		W Elevation View	
			
		N Elevation View	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# West Hills Intermediate

Pendleton SD 16

Umat\_sch28B

Building Type	County
School	Umatilla
Street	
1700 NW 15th Dr	
City	State Zip
Pendleton	OR 97801
Latitude	Longitude
45.67757	118.80615
Tracking Code	Inspection Date
RVS in 2006	8/15/2006



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	0	0	0	0	-0.8	0	0	2.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

West Hills Intermediate

## Final RVS Score

Final Type	Final Score
RM1	2.8

## FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

# West Hills Intermediate

Umat\_sch28B

Enrollment 182	Year Built (Field Verified) 1958	Year Built (Alt. Source) 1958	Est. Decade Built 1970
Total Area (square ft)	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	
 N Elevation View			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# West Hills Intermediate

Pendleton SD 16

Umat\_sch28C

Building Type	County
School	Umatilla
Street	
1700 NW 15th Dr	
City	State Zip
Pendleton	OR 97801
Latitude	Longitude
45.67712	118.80563
Tracking Code	Inspection Date
RVS in 2006	8/15/2006



Seismicity Zone: Moderate

**FEMA 154 Rapid Visual Screening Score Card**

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	0	0	0	1.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

West Hills Intermediate

**Final RVS Score**

Final Type	Final Score
RM1	1.1

**FEMA-154 Collapse Potential**

Moderate (>1%)
----------------



**OregonGeology**

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# West Hills Intermediate

Umat\_sch28C

Enrollment 182	Year Built (Field Verified) 1958	Year Built (Alt. Source) 1958	Est. Decade Built 1970
Total Area (square ft)	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners:Other (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: Single Change None None	
Falling Hazards None None None		Poor Conditions None None None	