


Athena-Weston Middle School

Athena-Weston SD 29RJ

Umat_sch31A

Building Type	County	
School	Umatilla	
Street		
333 Normal St		
City	State	Zip
Weston	OR	97886
Latitude	Longitude	
45.81259	118.42201	
Tracking Code	Inspection Date	
RVS in 2006	8/4/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	URM	3.4	-1.5	-0.5	-0.4	0	0	0	0	1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Athena-Weston Middle School

Final RVS Score

Final Type	Final Score
URM	1

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Athena-Weston Middle School

Umat_sch31A

Enrollment 133	Year Built (Field Verified) 1927	Year Built (Alt. Source) 1927	Est. Decade Built 1920
Total Area (square ft) 73905	Number of Stories 2	Basement	Pounding Potential Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: T shaped		Steps in Elevation View: Single Change	
Reentrant Corners: Other		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
Out of Plane Lateral-Force-Resistance Elements		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
W	Field Verified Year Built	NW	Vertical Irregularity Secondary
		W	Other
			
NE	Elevation View	SE	Elevation View



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Athena-Weston Middle School

Athena-Weston SD 29RJ

Umat_sch31B

Building Type	County
School	Umatilla
Street	
333 Normal St	
City	State Zip
Weston	OR 97886
Latitude	Longitude
45.81229	118.42225
Tracking Code	Inspection Date
RVS in 2006	8/4/2006



Athena-Weston Middle School

Final RVS Score

Final Type	Final Score
RM1	1.1

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Athena-Weston Middle School

Umat_sch31B

Enrollment 133	Year Built (Field Verified) 1927	Year Built (Alt. Source) 1927	Est. Decade Built 1950
Total Area (square ft)	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
Reentrant Corners: Other		Steps in Elevation View: Single Change	
None		Building On Hill or Sloped Site	
Falling Hazards		Poor Conditions	
None		Cracks	
None		None	
None		None	
			
N	Vertical Irregularity Tertiary	S	Poor Condition



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Athena-Weston Middle School

Athena-Weston SD 29RJ

Umat_sch31C

Building Type	County
School	Umatilla
Street	
333 Normal St	
City	State Zip
Weston	OR 97886
Latitude	Longitude
45.81292	118.42214
Tracking Code	Inspection Date
RVS in 2006	8/4/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	0	0	0	1.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Athena-Weston Middle School

Final RVS Score

Final Type	Final Score
RM1	1.1

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Athena-Weston Middle School

Umat_sch31C

Enrollment 133	Year Built (Field Verified) 1927	Year Built (Alt. Source) 1927	Est. Decade Built 1960
Total Area (square ft)	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities Steps in Elevation View: Single Change Building On Hill or Sloped Site None	
Falling Hazards None None None		Poor Conditions None None None	
			
N Elevation View		N Seismic Upgrade	
			
		W Elevation View	
			
SW Elevation View			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries