

Building Type		County	
Fire - RFPD		Union	
Street			
10200 S McAlister Rd			
City	State	Zip	
La Grande	OR	97850	
Latitude		Longitude	
45.3395		118.04569	
Tracking Code		Inspection Date	
RVS in 2006		8/4/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S3	3.8	0	-0.5	0	0	0	-1	0	2.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

LaGrande RFPD

Final RVS Score

Final Type

Final Score

S3

2.3

FEMA-154 Collapse Potential

Low (<1%)



Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1992	1992	1990
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
2268	1	No	No

Plan Irregularities	Vertical Irregularities
Torsion: Eccentric Stiffness	None
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



NE Elevation View



NW Elevation View



SW Elevation View