

Cove RFPD

Unio_fir06A

Cove RFPD

Building Type Fire - RFPD	County Union	
Street 607 Main		
City Cove	State OR	Zip 97824
Latitude 45.29684	Longitude 117.81192	
Tracking Code RVS in 2006	Inspection Date 8/14/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S3	3.8	0	-0.5	0	0	0	0	0	3.3
Secondary	RM1	3.6	-2	-0.5	0	0	0	0	0	1.1
Tertiary		0	0	0	0	0	0	0	0	0

Cove RFPD

Final RVS Score

Final Type	Final Score
RM1	1.1

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: L Shaped		Vertical Change in Structural Type (Soft over Stiff)	
Reentrant Corners: Other		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
Torsion: Eccentric Stiffness		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
 W Primary Structural Type		 NE Plan Irregularity Primary	

