

Union Emergency Services - Fire

Unio_fir07A

City of Union City

Building Type		County	
Fire - City		Union	
Street			
570 E Beakman			
City	State	Zip	
Union	OR	97883	
Latitude		Longitude	
45.2081		117.86059	
Tracking Code		Inspection Date	
RVS in 2006		8/14/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S3	3.8	0	-0.5	0	0	0	-1	0	2.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Union Emergency Services - Fire

Final RVS Score

Final Type

Final Score

S3

2.3

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Union Emergency Services - Fire

Unio_fir07A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1992	1990
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
6000	1	No	No

Plan Irregularities	Vertical Irregularities
Torsion: Eccentric Stiffness	None
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



NW Elevation View