

Grande Ronde Hospital - LaGrande

Unio_hos01A

Private, NFP

Building Type		County	
Hospital		Union	
Street			
900 Sunset Dr			
City	State	Zip	
La Grande	OR	97850	
Latitude		Longitude	
45.31964		118.10541	
Tracking Code		Inspection Date	
RVS in 2006		8/3/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C1	3	-2	-0.5	0	0	0	-1	0	-0.5
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Grande Ronde Hospital - LaGrande

Final RVS Score

Final Type

Final Score

C1

-0.5

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Grande Ronde Hospital - LaGrande

Unio_hos01A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1966	1967
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	Yes	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: T shaped	Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)
Reentrant Corners: Other	Soft Story
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



E Elevation View



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Grande Ronde Hospital - LaGrande

Unio_hos01B

Private, NFP

Building Type		County	
Hospital		Union	
Street			
900 Sunset Dr			
City	State	Zip	
La Grande	OR	97850	
Latitude		Longitude	
45.31964		118.10582	
Tracking Code		Inspection Date	
RVS in 2006		8/3/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C1	3	-2	-0.5	0	0	0	-1	0	-0.5
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Grande Ronde Hospital - LaGrande

Final RVS Score

Final Type

Final Score

C1

-0.5

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1981	1966	1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	3	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Building On Hill or Sloped Site
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



S Primary Structural Type
basement



S Elevation View



SW Elevation View

Grande Ronde Hospital - LaGrande

Unio_hos01C

Private, NFP

Building Type		County	
Hospital		Union	
Street			
900 Sunset Dr			
City	State	Zip	
La Grande	OR	97850	
Latitude	Longitude		
45.31952	118.10653		
Tracking Code	Inspection Date		
RVS in 2006	8/3/2006		



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C1	3	-2	-0.5	0	0	0	-1	0	-0.5
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Grande Ronde Hospital - LaGrande

Final RVS Score

Final Type

Final Score

C1

-0.5

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1986	1966	1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	3	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Steps in Elevation View: Very Irregular Changes (Adjacent Building/Ent
Reentrant Corners: Other	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



N Elevation View



Grande Ronde Hospital - LaGrande

Unio_hos01D

Private, NFP

Building Type		County	
Hospital		Union	
Street			
900 Sunset Dr			
City	State	Zip	
La Grande	OR	97850	
Latitude		Longitude	
45.31928		118.10609	
Tracking Code		Inspection Date	
RVS in 2006		8/3/2006	

Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	-3	-0.5	0	1.6	0	-1.2	0	1.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Grande Ronde Hospital - LaGrande

Final RVS Score

Final Type

Final Score

W2

1.7

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1991	1966	1990
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	3	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Building On Hill or Sloped Site
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None