


# Union City Police Dept

City of Union City

Unio\_pol01A

Building Type Police-City	County Union	
Street 342 S Main St		
City Union	State OR	Zip 97883
Latitude 45.2074	Longitude 117.86576	
Tracking Code RVS in 2006	Inspection Date 8/14/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	URM	3.4	-1.5	0	-0.4	0	0	-0.8	0	0.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Union City Police Dept

### Final RVS Score

Final Type	Final Score
URM	0.7

### FEMA-154 Collapse Potential

High (>10%)




OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Union City Police Dept

Unio\_pol01A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1891	1891	Pre 1900
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
5536	2	No	Yes
Plan Irregularities		Vertical Irregularities	
None		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
None		None	
None		None	
Falling Hazards		Poor Conditions	
Parapets: Unreinforced Across Front of Building		None	
None		None	
None		None	
			
W	Field Verified Year Built	W	Elevation View
			
		W	Pounding Potential



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries