

OSP - La Grande Patrol

Oregon State Police

Unio_pol02A

Building Type		County	
Police - State		Union	
Street			
3014 Island Ave			
City	State	Zip	
La Grande	OR	97850	
Latitude		Longitude	
45.33514		118.06291	
Tracking Code		Inspection Date	
RVS in 2006		8/4/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	0	-0.5	0	0	-0.8	0	0	3.5
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

OSP - La Grande Patrol

Final RVS Score

Final Type

Final Score

W2

3.5

FEMA-154 Collapse Potential

Low (<1%)

OSP - La Grande Patrol
3014 Island Ave.
La Grande, OR 97850



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1973	1973
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
26596	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: L Shaped	None
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



NE Elevation View



SE Elevation View



SW Elevation View