

La Grande City Police Dept

City of La Grande

Unio_pol03A

Building Type	County
EOC-Public Safety Answering P	Union
Street	
1109 K Ave	
City	State Zip
La Grande	OR 97850
Latitude	Longitude
45.32163	118.09473
Tracking Code	Inspection Date
RVS in 2006	8/3/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	0	-1.2	0	-0.1
Secondary	W2	4.8	-3	-0.5	0	1.6	0	-1.2	0	1.7
Tertiary		0	0	0	0	0	0	0	0	0

La Grande City Police Dept

Final RVS Score

Final Type	Final Score
RM1	-0.1

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

La Grande City Police Dept

Unio_pol03A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1977	1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Single Change	
None		None	
None		None	
Falling Hazards		Poor Conditions	
Other: Smokestack		None	
None		None	
None		None	
			
NE Elevation View		SE Plan Irregularity Primary	
		SE Primary Structural Type	
			
SW Elevation View		SW Falling Hazard	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries