

Joseph PD

City of Joseph

Wall_pol02A

Building Type Police - City	County Wallowa	
Street 201 N Main St		
City Joseph	State OR	Zip 97846
Latitude 45.35357	Longitude 117.23024	
Tracking Code RVS in 2006	Inspection Date 8/12/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	0	0	-0.4	0	0	-1.2	0	2
Secondary	RM1	3.6	0	0	-0.4	0	0	-1.2	0	2
Tertiary		0	0	0	0	0	0	0	0	0

Joseph PD

Final RVS Score

Final Type	Final Score
C2	2

FEMA-154 Collapse Potential

Moderate (>1%)



Oregon Geology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1940
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	Yes
Plan Irregularities		Vertical Irregularities	
None		None	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
SW Elevation View			

